Operating Instructions (DT-3)

Functions

- Indoor and outdoor temperature measure function.
- Indoor relative humidity & comfort level indicator.
- Maximum and minimum temperature and indoor humidity memory.

Parameters

- Indoor measurement range(-30℃ to 50℃).
- Outdoor measurement range(-50℃ to 70℃).
- Humidity measurement range(20%RH to 99%RH).

Operation Description

- Indoor/Outdoor Temperature & Humidity.

◆ In indoor temperature,press MAX key will display the maximum indoor temperature and maximum indoor humidity.Press MIN key will display the minimum indoor temperature and minimum indoor humidity.

◆ In outdoor temperature,press MAX key will display the maximum outdoor temperature and maximum indoor humidity.Press MIN key will display the minimum outdoor temperature and minimum indoor humidity.

- Press RESET key will clear the Indoor/Outdoor Temperature & Humidity memory.
- Comfort indicators will display the level as comfortable,wet or dry.The table is shown below:

Humidity(%)			
	WET	WET	WET
70(%)	NO COMFORT	COMFORT	NO COMFORT
40(%)	DRY	DRY	DRY
		20℃	25℃ Temperature(℃)