

# TPM-30 Instruction

## Technical parameter:

- Temperature measuring range:  $-50^{\circ}\text{C} \sim +70^{\circ}\text{C}$
- Resolution:  $> -20^{\circ}\text{C}$ ,  $0.1^{\circ}\text{C}$ ;  $\leq -20^{\circ}\text{C}$ ,  $1^{\circ}\text{C}$
- Power supply: 1.5VDC; Button battery(LR44)
- Accuracy:  $\pm 1^{\circ}\text{C}$

## Use Description:

- Open the battery cover, put into one button battery. Please notice on the polarity, do not mistake. Display temperature immediately when install the battery.
- Display  $\text{H}^{\circ}\text{C}$  when  $\geq 70^{\circ}\text{C}$ ; Display  $\text{L}^{\circ}\text{C}$  when  $\leq -50^{\circ}\text{C}$  (in temperature measuring state)